

GREGORY S. BELL

Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining JOHN R. BAZA Division Director

Minerals Inspection Report

06/04/2014 Report Date: Mine Status: Active Mine Name: Last Chance 25 & 26 Permit Number: M/015/0061 Operator Name: : Western Clay Company Inspection Date: 05/29/2014 Permit Fees: Paid **Bond Amount:** \$55,600 Inspector(s): Wayne Western Inspection Time: 1:20 - 1:40 pm Weather: warm and cloudy **Bond Escalation:** 07/26/2016 Attendee(s): none 04/21/2011 Inspection Purpose: Routine inspection Prior Inspection:

Conclusions and Recommendations


The site is stable. The site has been inactive for five years. The Division should request that the Operator state their intension.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds		
	Bond and permit fees current		
2.	Public Safety (shafts, adits, trash, signs, highwalls)		
	The site is stable and thre are no major hazards to the public		
3.	Protection of Drainages/Erosion Control		
	No erosion		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
6.	Reclamation		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)		
8.	Soils		
9.	Revegetation		
10.	Other ector's Signature: Walput White		


File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M015-Emery/M0150061-Lastchance/inspection/INSP05292014.pdf




Inspected: 05/29/2014




Pad area



Pad area and material that is stockpiled



Stockpiled material



Over view of site

